

METHODS AND APPARATUS FOR ANOMALY
DETECTION

ABSTRACT OF THE DISCLOSURE

A method for detecting an anomaly includes performing a computed tomography (CT) scout scan to obtain data, and supplying the obtained data to a radiographic computer aided detection (CAD) algorithm.